

Common inspection catches

- Drawings do not match actual construction
- Incorrect vertical rebar placement (must be hooked & tied into place)
- Anchor bolt placement
- Need for treated wood
- Truss lateral bracing
- Incorrect rafter/joist spans
- Joists cut for plumbing/HVAC
- Undersized headers
- Undersized framing for plumbing
- Sloping grade away from building (drainage)
- Foundation clearance to grade
- Insulation ratings
- Strapping and hangers (framing/plumbing/mechanical)